



ZYDOSIL[®] CONC

International

ACH / INST / INTL-005

Swimming Pool Walkway of a stylish hotel in Guatemala City

The Challenge

The Westin Camino Real Hotel is in the center of Guatemala City. In their swimming pool walkway area there were problems related to blackening of the stone claddings as a result of continuous exposure to water. It was asking for repeated cleaning which was cumbersome and expensive.



Project Details:

Name: Hotel Westin Camino Real
Associate: Fassi Chemical Inc., Miami, Florida
Job Quantum: 5,000 ft² Stone Cladded Surface
Products: Zycosil
Period: January 2008



Zycosil was introduced to the hotel authorities through a table-top demonstration followed by a small mock-up at the actual site location.

After evaluation of the product capabilities, they decided to carry out Zydex Organosilane treatment on the patio area and the walkways around the swimming pool.

The job was executed by professionally trained technicians of our associate which left the customer completely satisfied.

BENEFITS

Eliminates:

- Fungal Growth
- Rebar Corrosion
- Alkali Silica Reaction
- Carbonation
- Dampness

Reduces:

- Efflorescence
- Dust Accumulation

Zydex[®]

info@zydexindustries.com
www.zydexindustries.com

ZYDEX INDUSTRIES PVT. LTD.
Zydex House, 61, Gotri-Sevasi Road
Vadodara - 391 101, INDIA

ZYDEX INC.
106, Kitty Hawk Drive, Morrisville
NC 27560, USA